Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW0358/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW0358

CLIENT INFORMATION

Client Name: 12012NW0358 Address:

Client ID: 12012NW0358 , 38320

Alt. Client ID: Benton

CLIENT CONTACT INFORMATION

12012NW0358 Applicant/Person of ✓

Record

<u>AGENCY INFORMATION</u>

Agency: Northwest TN EDC Agency Phone: (731) 364-3228

Address: 231 S. Wilson Street Fax:

Dresden, TN 38225 Email Address:

Agency Contact: Radford, Randy Work Phone: (615) 686-3245

Cell Phone: (615) 335-7428

Email Address: Randy@energyhoundz.com

Company Name & License Number:	
Contractor's Signature	

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Client Name: 12012NW0358 Client ID: 12012NW0358 Alt. Client ID: Benton Work Order (Bid Form)
Work Order Name: WO/12012NW0358/1
Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.6.0 Page 1 of 9

Measures

Measure 1 Reglaze All Windows			Componen	its		ı	nspected
Comment							
			Estimated	1		Actual	
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor		1					
2 Windows		1					
Other Detail							
		Measur	e Sub Total:] :	Sub Total:	
Field Notes:							
	141 0/411			_			
Measure 2 Replace Attic Access Door			Componen	ıts		ı	nspected
Plywood and Paint Dark B			Componen	ıts		ı	nspected
Plywood and Paint Dark Bi (approx. 17x20	rown	l o o ulor	-			,	Inspected
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door	rown	Insulat	-		ccess	ı	Inspected
Plywood and Paint Dark Bi (approx. 17x20	rown	Insulat	ion on Top	of Attic A	ccess		Inspected
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door	rown		ion on Top o	of Attic A		Actual	Inspected
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door	rown r and Glue	Insulat	ion on Top	of Attic A	CCESS Qty		
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment	rown r and Glue	Qty	ion on Top o	of Attic A		Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment	rown r and Glue	Qty	ion on Top o	of Attic A		Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor	rown r and Glue	Qty 1	ion on Top o	of Attic A		Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors	rown r and Glue	Qty 1	ion on Top o	of Attic A		Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors	rown r and Glue	Qty 1	ion on Top o	of Attic A		Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors	r and Glue Units	Qty 1 1	ion on Top o	of Attic A	Qty	Actual	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors	r and Glue Units	Qty 1 1	Estimated Unit Cost	of Attic A	Qty	Actual Unit Cost	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors Other Detail	r and Glue Units	Qty 1 1	Estimated Unit Cost	of Attic A	Qty	Actual Unit Cost	
Plywood and Paint Dark Bi (approx. 17x20 Comment Install 2 Latches to Secure Door Door # Material / Labor Description / Comment 1 Labor 2 Doors Other Detail	r and Glue Units	Qty 1 1	Estimated Unit Cost	of Attic A	Qty	Actual Unit Cost	

Client Name: 12012NW0358 Client ID: 12012NW0358 Alt. Client ID: Benton

Work Order (Bid Form)
Work Order Name: WO/12012NW0358/1
Report Run On: 5/24/2010

DOE Weatherization Assistant Version 8.6.0 Page 2 of 9

Measu	re 3 Wea	therstrip Around All D	oors		Componen	ts			Inspected
Comme	ent								
					Estimated			Actual	
# <i>Materia</i> 1 Labor	al / Labor	Description / Comment	Units	Q ty 1	Unit Cost	Total	Qty	Unit Cost	Total
2 Doors	i			1					
Other De	etail								
				Measur	e Sub Total:		,	Sub Total:	
Field N	lotes:								
Measu	re 4 Infil	tration Redctn			Componen	ts			Inspected
Commo	nt -Air Sea	l Around Windows							
001111110		I Trim Around Doors							
		Il Attic Access in Bedro	om Clocot						
		Il Around 2 Window A/C							
				odroom	Door				
		I Hole in Kitchen Ceiling				(itahan (A	nnrov		
		I Separation Between C	JOWN WIOIG	ing and	i Celling in r	dichen (A	фргох.		
	54 sq. ft	<i>)</i> Il Holes Around and Abo	ova Braaka	r Boy ir	Dothroom				
						om (Annr	ov 60		
		Caulk Top and Bottom o	I CIOWII IVIC	olding c	on Living Roo	ліі (Арріі	0x. 60		
	sq. ft.)				Estimated	,		Actual	
H Matari	al / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
		Description/ Comment	Omis	Qty	Omit Oost	Total	Q (y	Omit Oost	Total
Labor									
0 Misce	llaneous Su	Infiltration Reduction	Each	1					
Other De	4-11								
Other De	etail								
Other De	etail								
Other De	etail								
Other De	etail			Measur	e Sub Total:			Sub Total:	
Other De				Measur	e Sub Total:			Sub Total:	
				Measur	e Sub Total:			Sub Total:	
				Measur	e Sub Total:			Sub Total:	
				Measur	e Sub Total:			Sub Total:	

Client Name: 12012NW0358 Client ID: 12012NW0358 Alt. Client ID: Benton

Work Order (Bid Form)
Work Order Name: WO/12012NW0358/1

DOE Weatherization Assistant Version 8.6.0 Page 3 of 9

Report Run On: 5/24/2010

Measure 5 Comment	DWH Pipe Insulation			Componen	ts		,	Inspected
				Estimated	<u> </u>		Actual	
# Material / Labo	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
3 Other	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:		,	Sub Total:	
Measure 6 I	Fill Ceiling Cavity			Componen	<i>t</i> s A1		,	Inspected
	Fill Ceiling Cavity			Componen Estimated			Actual	Inspected
	-	Units	Qty	-		Qty		Inspected Total
Comment	-	Units	Qty	Estimated	1	Qty	Actual	
Comment # Material / Labo Labor	Description / Comment Attic Insulation - Blown	<i>Units</i> SqFt	Qty 769	Estimated	1	Qty	Actual	
# Material / Labor Labor Insulation	or Description / Comment			Estimated	1	Qty	Actual	
Comment # Material / Labo Labor	Description / Comment Attic Insulation - Blown			Estimated	1	Qty	Actual	
# Material / Labor Labor Insulation	Description / Comment Attic Insulation - Blown			Estimated	1	Qty	Actual	
# Material / Labor Labor Insulation	Description / Comment Attic Insulation - Blown	SqFt	769	Estimated	1		Actual	
# Material / Labor Labor 1 Insulation	Description / Comment Attic Insulation - Blown	SqFt	769	Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor Labor 1 Insulation Other Detail	Description / Comment Attic Insulation - Blown	SqFt	769	Estimated Unit Cost	1		Actual Unit Cost	

C	Measure 7 DWI Comment	H Tank Insulation			Componen			1	Inspected
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
3	Other	DHW Tank Insulation	Each	1					
	Other Detail			1					
L									
				Measur	e Sub Total:		,	Sub Total:	
	Measure 8 Wall	I Insulation							
					Componen				Inspected
					Estimated	,		Actual	
#	<i>Material / Labor</i> Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
# 1	Labor	Description / Comment			Estimated	,	Qty	Actual	
	Labor		<i>Units</i> SqFt	Qty	Estimated	,	Qty	Actual	
1	Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	,	Qty	Actual	
1	Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	,	Qty	Actual	
1	Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	,	Qty	Actual	
1	Labor	Description / Comment Wall Insulation - Blown	SqFt	Qty 174.3	Estimated	,		Actual	

Measure 9 Wa Comment	II Insulation			Componen				Inspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	138.6					
Other Detail			,					
			Measure	Sub Total:		;	Sub Total:	
Measure 10 Wa	Il Insulation							
	ii iiisulatioii			Componen				Inspected
				Estimated			Actual	Inspected
	Description / Comment	Units	Qty	-		Qty		Inspected Total
# Material / Labor Labor		Units		Estimated	<u> </u>	Qty	Actual	
Labor		Units SqFt		Estimated	<u> </u>	Qty	Actual	
Labor	Description / Comment Wall Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty	Estimated	<u> </u>	Qty	Actual	
Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 112.6	Estimated	<u> </u>		Actual	
Labor 1 Insulation	Description / Comment Wall Insulation - Blown		Qty 112.6	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
1 Insulation Other Detail	Description / Comment Wall Insulation - Blown		Qty 112.6	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

	I Insulation			Componen	ts WL5		ı	Inspecte
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	146.6					
Other Detail								
]] []		
] []		
			Measure	e Sub Total:			Sub Total:	
Measure 12 CO Comment	Monitor is Needed				4			l
				Componen				Inspecte
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspecte Total
		<i>Units</i> Each		Estimated		Qty	Actual	
# Material / Labor Health and Safety Labor			Qty	Estimated		Qty	Actual	
1 Health and Safety	CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Health and SafetyLabor	CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Health and SafetyLabor	CO monitor	Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
Health and SafetyLabor	CO monitor	Each	Qty 1 1	Estimated			Actual	

•	Measure 13 Install Deadbolt on Back Door DR2 (Safety Issue)				Componen	ts			Inspected
C	omment								
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Miscellaneous Su			1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
		all Deadbolt on Front Do	oor DR1		Componen				Inspected
C	(Safe		oor DR1	Qty	Componen Estimated Unit Cost		Qty	Actual Unit Cost	Inspected
<i>C</i> #	(Safe	ety Issue)		Qty 1	Estimated	1	Qty	Actual	
C #	(Safe comment Material / Labor	ety Issue)			Estimated	1	Qty	Actual	
C # 1	(Safe comment Material / Labor Labor	ety Issue)		1	Estimated	1	Qty	Actual	
C # 1	(Safe comment Material / Labor Labor Miscellaneous Su	ety Issue)		1	Estimated	1	Qty	Actual	
C # 1	(Safe comment Material / Labor Labor Miscellaneous Su	ety Issue)	Units	1	Estimated Unit Cost	1		Actual Unit Cost	
C # 1	(Safe comment Material / Labor Labor Miscellaneous Su	ety Issue)	Units	1	Estimated	1		Actual	

	<i>Measure</i> 15 Smo	ke Detector is Needed			Componen	its			Inspected	
C	omment									
					Estimated	1		Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety	Smoke detector	Each	1						
2	Labor	Labor	Hour	1						
(Other Detail			1	1					
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
L										
			Work Or	rder Gra	nd Total:		Gran	d Total:		